Riverbank Erosion Comparison along the Connecticut River









October 2012

prepared for



Table of Contents

Table of Contents	i
Executive Summary	. iii
<u>1. Introduction</u>	1
2. Connecticut River Reaches	6
3. Natural Riverine Geomorphology	7
4. Current State of Riverbank Erosion along the Connecticut River	9
4.1 Free-Flowing reach	9
4.2 Connecticut River Impoundments	. 16
4.2.1 Riverbank Erosion – Bellows Falls Impoundment	.16
4.2.2 Riverbank Erosion – Vernon Impoundment	. 21
4.2.3 Riverbank Erosion – Turners Falls Impoundment	. 25
4.2.4 Riverbank Erosion – Holyoke Impoundment	. 30
5. Discussion of Erosion along the Connecticut River	. 35
<u>6. Conclusions</u>	. 47
7. References	. 49

List of Tables

Table 1. Total length of erosion from 1979 USACE maps	4
Table 2. Dams along the Connecticut River	6
Table 3. 2008 FRR Summary Groups 2	25

List of Figures

Figure 1. Connecticut River
Figure 2. Erosion Sites - Keene and Bellows Falls Quadrangles, "Connecticut River
Streambank Erosion Study Massachusetts, New Hampshire and Vermont," 1979 5
Figure 3. Connecticut River profile
Figure 4. Northern Connecticut River
Figure 5. Erosion in channelized reach
Figure 6. Erosion of glacial outwash deposit
Figure 7. Erosion due to bar formation
Figure 8. Erosion due to agricultural practices
Figure 9. Riverbank erosion – Pittsburg to Gilman
Figure 10. Example of Riverbank Characteristics - Northern, Free-Flowing Reach . 15
Figure 11a. Erosion Sites – Bellows Falls Impoundment, 1997
Figure 11b. Erosion Sites – Bellows Falls Impoundment, 1997

Figure 11c. Erosion Sites – Bellows Falls Impoundment, 1997	19
Figure 12. Riverbank erosion comp, Bellows Falls Impoundment – Location 8	20
Figure 13a. Erosion Sites – Vernon Impoundment, 1997	22
Figure 13b. Erosion Sites – Vernon Impoundment, 1997	23
Figure 14. Riverbank erosion comp, Vernon Impoundment, 1997-2008, Loc I	24
Figure 15. Erosion in Vernon Impoundment, 1954	21
Figure 16. Example of Full River Reconnaissance Map – Turners Falls Imp	26
Figure 17. Comparison of Skalski Site pre 2004 to 2008	28
Figure 18. Natural stabilization processes 1996-2008 downstream of Vernon Dam .	29
Figure 19a. Location of Erosion Sites – Holyoke Impoundment, 1997	31
Figure 19b. Location of Erosion Sites – Holyoke Impoundment, 1997	32
Figure 19c. Location of Erosion Sites – Holyoke Impoundment, 1997	33
Figure 20. Riverbank Erosion Holyoke Impoundment, Site D 1997-2008	34
Figure 21. Water level fluctuations at four hydropower impoundments	40
Figure 22. Gage height near Dalton, NH 9/1/2012-10/23/2012	41
Figure 23. Gage height at West Lebanon, NH 9/1/2012-10/23/2012	41
Figure 24. Gage height at North Walpole, NH 9/1/2012-10/23/2012	42
Figure 25. Gage height at Montague City, MA 9/1/2012-10/23/2012	42
Figure 26. Water Level Fluctuations in Turners Falls Impoundment, 7/11-16/1997 .	43
Figure 27. Water level fluctuations in upper Turners Falls Impoundment due	to
operations at Vernon, December 2000	43
Figure 28. Water level fluctuations at Northfield Mountain Tailrace, Dec 2000	44
Figure 29. Yellowstone River – Yellowstone National Park	45
Figure 30. Middle Fork of the Flathead River – Glacier National Park	45

Appendices

Appendix A – Location of Erosion Sites in the Study Reach

Appendix B – Erosion and Bank Composition Maps – Northern Connecticut River

Appendix C – Bellows Falls Pond Inspection, 1991

Appendix D – Bellows Falls Impoundment Erosion Site Comparison: 1997-2008

Appendix E – Vernon Impoundment Erosion Site Comparison: 1997-2008

Appendix F – Examples of Vernon Impoundment Erosion in 1954

Appendix G – Turners Falls Impoundment FRR Summary Maps, 2008

Appendix H – Turners Falls Impoundment, Photos of Repaired Erosion Sites

Appendix I – Turners Falls Impoundment, Natural Stabilization Processes

Appendix J – Holyoke Impoundment Erosion Site Comparison: 1997-2008

Appendix K – Riverbank Erosion on Other Rivers

Riverbank Erosion Comparison along the Connecticut River

Simons & Associates October 2012

Executive Summary

Rivers are dynamic features meaning that lateral migration, channel shifting, and changing position are processes that occur to varying degrees along their path. The fact that channels migrate, shift, and otherwise change position translates directly into riverbank erosion. Such is the case with the Connecticut River as it flows through Vermont, New Hampshire, Massachusetts, and Connecticut. Erosion has been and is a concern for many people and groups all along the river corridor. Several studies have been conducted regarding riverbank erosion of the Connecticut River. Information and data on this subject are available from a variety of sources over a period of more than 50 years although most of the information covers the more recent decades. A review, evaluation, and comparison of riverbank erosion along the Connecticut River was conducted based on available reports from a variety of sources coupled with some recent compilation of photographic evidence of erosion in the Bellows Falls, Vernon, and Holyoke Impoundments as well as the recently completed full river reconnaissance (FRR) of the Turners Falls Impoundment (Simons & Associates, 2009). The objective of this study is to compare riverbank erosion between the various impoundments and freeflowing reaches along the Connecticut River and to draw conclusions based on the observations and comparisons.

The Connecticut River consists of several different segments ranging from un-impounded or free-flowing reaches, primarily in the northern section of the river; to a series of pools formed by dams, primarily in the middle and southern sections of the river. The study reach for this comparison of riverbank erosion extends from Pittsburg, NH in the north downstream to Holyoke Dam. Over the approximate 240 mile study reach, the Connecticut River flows through 15 currently-existing dams with associated impoundments, as well as free-flowing sections.

Riverbank features and characteristics vary considerably along the length of the river. While portions of the river consist of bedrock outcrops that are very stable, much of the riverbanks consist of hillsides or alluvial material that is formed primarily of silt to sand sized material. There are areas that consist of gravel to cobble sized material that are generally less erodible but still are alluvial or transportable by fluvial processes nonetheless. Much of the riverbanks are quite well vegetated, which generally adds to riverbank stability, although there are segments where a range of erosion and masswasting processes remove or damage vegetation and associated riparian land.

Riverbank erosion was compared among various reaches to the extent feasible with available data as well as through photographs taken over the years at erosion sites. The comparison reveals the following key points:

- The segment of river with the greatest extent of eroding riverbanks is the unimpounded northern reach (Pittsburg, NH down to Gilman Dam). At the time of the available study (Field, 2004), 48.4% of the riverbanks were experiencing moderate or more significant erosion. Riverbanks that had been rip-rapped covered 17.1% of the length of the river.
- Several erosion sites were identified and photographed in the Bellows Falls, Vernon, Turners Falls, and Holyoke Impoundments in 1997, and again in 2008. All of the erosion sites in 1997 in the Bellows Falls and Holyoke Impoundments and all but one of the 1997 erosion sites in the Vernon Impoundment remain in essentially the same state of erosion when photographed in 2008, many of which are significant in both size and severity. In contrast, most of the erosion sites identified in the Turners Falls Impoundment in 1998 have been stabilized and are no longer eroding as of 2008 (when previously identified erosion sites were re-photographed in 3 impoundment), with several additional erosion sites scheduled to be stabilized as part of the *"Erosion Control Plan for the Turners Falls Pool of the Connecticut River"* (1998, Simons & Associates) by 2012.
- In addition to direct stabilization of many of the erosion sites in the Turners Falls Impoundment that were identified in the 1998 Erosion Control Plan (ECP), there is evidence of some natural stabilization processes including increased upper bank vegetation and areas of dense low bank aquatic vegetation that are helping provide a degree of additional stability in some areas.
- Despite the fact that similar percentages of riverbank have been stabilized in the northern, free-flowing reach and in the Turners Falls Impoundment; the percentage of erosion in the Turners Falls Impoundment is only about one-third the extent of erosion that is occurring in the northern, free-flowing reach of the Connecticut River (16.7% compared to 48.4%).
- Because riverbank erosion in the Turners Falls Impoundment is significantly less than in the northern free-flowing reach, and erosion sites in other impoundments (Bellows Falls, Vernon, and Holyoke) have continued eroding from 1997 to 2008 while many erosion sites have been stabilized in the Turners Falls Impoundment along with some evidence of natural stabilization processes; it can be concluded that the riverbanks in the Turners Falls Impoundment are in the best condition (more stable and less eroding) than in any other part of the Connecticut River.
- The Turners Falls Impoundment, which experiences water level fluctuations due to a combination of run of river/peaking power and pumped-storage hydropower operations, has less riverbank erosion than the other impoundments (Wilder, Bellows Falls, Vernon, Holyoke) which only experience water level fluctuations resulting from run of river and peaking power operations and do

not experience additional fluctuations due to pumped-storage operations. The Turners Falls Impoundment also experiences significantly less erosion than the northern, free-flowing reach which has no hydropower operations and associated water level fluctuations. This implies that the additional water level fluctuations due to pumped-storage operation either do not adversely affect riverbank erosion to a significant degree and/or are being successfully handled through implementation of the ECP.

The Turners Falls Impoundment, experiences water level fluctuations due to a . combination of three hydroelectric projects: Vernon and Turners Falls which operate approximately 3/4ths of the time in peaking power generation mode and when flows exceed their hydraulic generation capacity, operate the remainder of the time in a run-of-river mode; and the Northfield Mountain Pumped Storage Project which operates in a peaking power mode. The other impoundments experience water levels fluctuations due to hydroelectric projects that operate in a peaking power generation mode combined with run-of-river (when hydraulic generation capacities are exceeded). The Turners Falls Impoundment experiences less riverbank erosion than the other impoundments (Wilder, Bellows Falls, Vernon, and Holyoke) which only experience water level fluctuations resulting from run of river and peaking power operations and do not experience additional fluctuations due to pumped-storage operations. The Turners Falls Impoundment also experiences significantly less erosion than the northern, free-flowing reach which has no hydropower operations and associated water level fluctuations. This implies that the additional water level fluctuations due to pumped-storage operation either do not adversely affect riverbank erosion to a significant degree and/or are being successfully handled through implementation of the ECP.

<u>1. Introduction</u>

Riverbank erosion has been a long-standing issue for people having varying interests and relationships with rivers. Simons and Senturk (1991) discuss the fact that some rivers migrate laterally as much as 10s, 100s, and even 1000s of feet per year through a process of riverbank erosion. They further state that *"Stable or static alluvial channels are the exception in nature."* Such is the case for the Connecticut River to varying degrees along its length. Several erosion-related studies have been conducted along the Connecticut River and this report summarizes findings from these studies as well as information obtained by Simons & Associates (S&A) over decades of involvement along this river. It is intended to develop an understanding of erosion along the river, and compare erosion along specific reaches over time.

The Connecticut River flows out of Quebec in a southerly direction from the Connecticut Lakes in northern New Hampshire, along the border between New Hampshire and Vermont, through western Massachusetts and central Connecticut into Long Island Figure 1 shows the path of the Connecticut River as it flows through New Sound. England. On its journey through New England, the river is impounded by 15 dams, some of which are equipped with hydropower facilities. A few of the dams create impoundments that are sufficiently large to seasonally re-regulate¹ river flows. Most dams on the Connecticut River are low-head facilities which form narrow impoundments that experience generally low water velocities at low flow and higher velocities with near full riverine conditions at high flows. In the headwater reaches of the Connecticut River, it flows through a series of small dams and lakes including the Connecticut Lakes down to Canaan Dam. The river then flows through an unimpounded or free-flowing reach downstream from Canaan Dam to the upper reaches of the impoundment formed by Gilman Dam. The river flows through a couple of large storage dams (Moore and Comerford) capable of re-regulating river flow due to the seasonal storage capacity of the associated reservoirs. Downstream of Comerford Dam, the river passes through several low-head dams having relatively narrow impoundments McIndoes and Dodge Falls, Wilder, Bellows Falls, Vernon, Turners Falls, and Holyoke. Downstream of Holyoke Dam, the river is free-flowing through Connecticut and into Long Island Sound.

Except for rare segments of the Connecticut River like the French King Gorge located in the Turners Falls Impoundment which consists of an extensive rock outcrop; the Connecticut River, through a significant portion of its length, is an alluvial river. An alluvial river consists of bank and bed material that the river itself transports, deposits, or erodes. An interesting characteristic of the Connecticut River is that fairly recently (in geologic time) it used to be a large lake (Lake Hitchcock) that formed as the little ice age (approximately 18,000 years ago) was ending and melting ice was blocked by a mass of sediment pushed up by the ice (Rittenour, 1999. As a result of the formation of a large lake, into which sediment deposited over a period of approximately 3000 years, much of the riverbank material of the Connecticut River consists of fine sediment that deposited in the lake. Field (2007) commented on the nature of riverbank sediments found in a reach

¹ Dams having sufficient storage capacity to store water during periods of high flow thereby reducing flood peaks for release during the low flow season.

of the Connecticut River describing them as being "naturally susceptible to erosion given their noncohesiveness and fine-grained texture." Alluvial rivers, consisting of materials



Figure 1. Connecticut River (after USGS NHD, USACE, NID)

that are periodically eroded, transported, or deposited; are – by definition, dynamic. Thus, various segments of riverbanks along the length of the Connecticut River are eroding, consistent with the dynamic nature of alluvial rivers especially considering the

non-cohesive, fine-grained riverbank soils – much of which is sediment that was deposited when the Connecticut River was a lake.

Several studies of riverbank erosion along the Connecticut River have been conducted on different parts of the river and from different sources some of which are listed below.

- "Observation of Erosion on Banks of the Connecticut River Bellows Falls to Vernon September 2-3, 1954," Connecticut River Power Company, 1954
- "Connecticut River Streambank Erosion Study Massachusetts, New Hampshire and Vermont," United States Army Corps of Engineers (USACE), 1979
- "Analysis of Bank Erosion at the Skitchewaug Site in the Bellows Falls Pool of the Connecticut River," Simons & Associates, 1992
- "Bellows Falls Pond Bank Inspection," May 31, 1991, New England Power Company
- "Discussion of Erosion at Vernon Station," Simons & Associates, 1996
- "Erosion Control Plan for the Turners Falls Pool of the Connecticut River," Simons & Associates, 1998
- "Fluvial Geomorphology Assessment of the Northern Connecticut River, Vermont and New Hampshire," Field Geology Services, 2004
- "Fluvial Geomorphology Study of the Turners Falls Pool on the Connecticut River between Turners Falls, MA and Vernon, VT," Field Geology Services, 2007
- "Full River Reconnaissance 2008 Turners Falls Pool, Connecticut River," Simons & Associates, 2008 (Other full river reconnaissance efforts were conducted by New England Environmental in 2001 and 2004)

These reports and other available information provide sources for the evaluation of erosion along the length of the Connecticut River.

The study which covered the greatest length of the Connecticut River (USACE, 1979) included Appendix A entitled, "*Locations of Erosion Sites in the Study Reach*" confirms that erosion sites are found along the length of the river studied (Appendix A of this report presents maps showing erosion along the study reach – see numbered segments,). An example of erosion sites found along the river shows segments of river (shown by dark black lines, numbered to identify each site) in Figure 2. Erosion sites 4 through 17A are indicated on the east bank of the river and sites 302 through 305 are found on the west bank.

The distribution of erosion sites along the river from this 1979 study were as follows: 54 upstream of the Wilder Dam, 8 between Bellows Falls and Wilder Dams, 28 between Vernon and Bellows Falls Dams, 13 between Turners Falls and Vernon Dams. While the simple number of erosion sites does not fully describe the severity or length of erosion within each segment; it does, however, indicate that erosion is found along the entire length of the river that was studied. Based on the maps in the 1979 study, the total length of eroded sites for each of the impoundments was determined (see Table 1).

Reach of Connecticut River	Miles of Erosion	
	(1979 USACE maps)	
Wilder Impoundment	19.84	
Bellows Falls Impoundment	4.05	
Vernon Impoundment	9.91	
Turners Falls Impoundment	3.13	

Table 1. Total length of erosion from 1979 USACE maps



A-14

Figure 2. Erosion Sites – Keene and Bellows Falls Quadrangles, "Connecticut River Streambank Erosion Study Massachusetts, New Hampshire and Vermont," 1979

In this document, the distribution and extent of erosion along the Connecticut River is compared between the various reaches based on previous documentation of erosion from a variety of sources as well as recent and previous photographic evidence of erosion where such information is available.

2. Connecticut River Reaches

The Connecticut River includes both riverine or free-flowing reaches as well as reaches impounded by dams. Table 1 summarizes Connecticut River dams and their height, listed in order from upstream to downstream. As noted in the table, a couple of these dams are breached and no longer form upstream impoundments. River reaches in the Connecticut River are primarily defined by the existence of dams and impoundments formed by these dams.

Dam	Dam Height (ft)
Moose Falls Flowage	10
Second Connecticut Lake Dam	28
First Connecticut Lake Dam	56
Murphy Dam (Lake Francis)	106
Canaan Dam	27
Lyman Falls Dam	Breached
Wyoming Dam	Breached
Gilman Dam	40
Moore Dam	178
Comerford Dam	170
McIndoe Falls Dam	25
Dodge Falls Dam	28
Wilder Dam	39
Bellows Falls Dam	57
Vernon Dam	60
Turners Falls Dam	35
Holyoke Dam	60

Table 2. D	Dams along	the Conn	ecticut River*
1 ao i v 2. D	and arong		

* Information primarily from Connecticut River Joint Commissions (CRJC)

A profile of the Connecticut River for most of its length is presented in Figure 3. As shown by this profile, much of the river is impounded behind a series of dams as listed above. The longest reach that is not impounded stretches downstream from Pittsburg to the Wyoming Valley (since Wyoming dam was breached).



Figure 3. Connecticut River profile (after, US Generation).

Dams generally reduce the river velocity, depending on the magnitude of river flow compared to the magnitude and extent of the impoundment storage volume. In addition to the main-stem dams, several United States Army Corps of Engineers flood control dams have been constructed on tributaries to the Connecticut River to reduce peak flows and flood damage.

3. Natural Riverine Geomorphology

Except for rare segments of the Connecticut River like the French King Gorge located in the Turners Falls Impoundment, which consists of extensive rock outcrop; the Connecticut River, through a significant portion of its length, is an alluvial river. An alluvial river consists of bank and bed material that the river itself transports, deposits, or erodes. Alluvial rivers, consisting of materials that are periodically eroded, transported, or deposited are – by definition, dynamic.

The dynamic nature of rivers is described in one of the foremost and well-known textbooks, <u>Fluvial Processes in Geomorphology</u> (Leopold, Wolman and Miller, 1964). Chapters of interest that indicate the dynamic nature of rivers include: Chapter 1 -"The Changing Scene," Chapter 3 -"Climate and Denudational Processes," Chapter 4 -"Weathering," Chapter 10 -"Drainage Pattern Evolution," Chapter 11 -"Channel Changes with Time," Chapter 12 -"Evolution of Hillslopes." Key words of note directly discuss the fact that rivers change: changing, denudational processes, weathering, evolution, changes with time. The aftermath of Hurricane Irene in 2011 provided a

recent and dramatic reminder of disruption and change that occurs in living with the dynamic nature of rivers. Leopold et al, discusses the continual adjustments of river systems through processes of aggradation, degradation, scour, deposition, and lateral migration; providing numerous examples of rivers that have historically experienced significant changes.

Even the concept of a river in equilibrium (as described below) does not mean that a river, so classified, is not changing. In discussing the concept of equilibrium in an ideal channel, Leopold et al state the following:

This analysis brings out an essential point. In the simplest stable natural channel with movable bed and banks, two conditions must be satisfied simultaneously – the transmission of the flow and the stability of the banks. Such a channel has been called "threshold" (Henderson, 1961, p. 112), describing the fact that each point on the perimeter is at the threshold of movement. In this hypothetical condition a channel could not transport sediment because the required increase in stress would cause erosion of the banks. In actuality a natural channel not only carries sediment but migrates laterally by erosion of one bank, maintaining on the average a constant channel cross section by deposition at the opposite bank. In this case the condition. The form of the cross section is "stable," meaning constant, but position of the channel is not.

Thus, an ideal natural channel in equilibrium essentially means that the channel size generally retains an overall unchanging average size, with erosion in one place balanced by deposition in another, resulting in a channel changing its position over time. Changing position, even while retaining overall average channel geometry, necessarily means riverbank erosion occurs even in such channels that are considered to be in equilibrium.

The concept of the dynamic nature of rivers is confirmed by another eminent geomorphologist (Schumm, 1977, <u>The Fluvial System</u>) states,

Frequently environmentalists, river engineers, and others involved in navigation and flood control consider that a river should be unchanging in shape, dimensions and pattern. This would be very convenient. However, an alluvial river generally is changing its position as a consequence of hydraulic forces acting on its bed and banks.

Archaeologists have provided clear evidence that the lateral shift of channels is completely natural and to be expected.

In summary, archaeological, botanical, geological, and geomorphic evidence supports the conclusion that most rivers are subject to constant changes as a normal part of their morphological evolution. As noted by some of the world's most renowned geomorphologists, even those river reaches considered to be in "equilibrium" are expected to experience lateral movement and adjustment which necessarily involves the process of riverbank erosion. To expect otherwise contradicts reality and denies extensive historic evidence on rivers throughout the world. Erosion is a natural process, even in channels in equilibrium that cannot and should not be totally controlled.

4. Current State of Riverbank Erosion along the Connecticut River

4.1 Free-Flowing Reach

The longest free-flowing reach of the Connecticut River extends from Pittsburg, NH downstream to Gilman Dam (excluding the small reach affected by Canaan Dam, see Figure 3). A study of the condition of the Northern Connecticut River through this largely unimpounded and primarily alluvial reach (Figure 4) was conducted by Field Geology Services (2004, "Fluvial Geomorphology Assessment of the Northern Connecticut River, Vermont and New Hampshire").



Figure 4. Northern Connecticut River (after Field, 2004)

As an integral part of this analysis, the river was evaluated regarding channel instabilities and erosion, as Field (2004) states that, "*Management of erosion problems must address, or at least recognize, the causes for erosion.*" He cites six primary causes for erosion in this unimpounded reach of the Connecticut River:

Six of the most important human and natural causes of erosion and channel instability are discussed below: 1) channelization; 2) land clearance and other human land use intributary watersheds; 3) continuing adjustments to deglaciation; 4) agricultural practices in the riparian zone; 5) dams; and 6) reforestation of hillslopes cleared in the 18th and 19th Century.

Field presents several figures illustrating the causes of erosion in this free-flowing reach of the river (see Figures 5-8).



Figure 5. Erosion in channelized reach (after Field, 2004)



Figure 6. Erosion of glacial outwash deposit (after Field, 2004)



Figure 7. Erosion due to bar formation (after Field, 2004)



Figure 8. Erosion due to agricultural practices (after Field, 2004)



The distribution of riverbank erosion through this reach was summarized by Field as shown in Figure 9; eroding banks are shown in red.

Figure 9. Riverbank erosion – Pittsburg to Gilman (after Field, 2004)

This reach of river in the study area *"is largely free flowing and unimpounded, unlike much of the river farther south.*" The report concludes:

A fluvial geomorphic assessment of the northern Connecticut River has revealed that 66 percent of the river's banks are either eroding, have been protected from erosion, or are susceptible to further erosion (Table 1).

Table 1 (from the aforementioned report) provides information on bank stability indicating that 25.8 % (42.62 miles) of the length was "Eroding," and 22.6% (37.26 miles) was "Moderately eroding." Based on this information, this free-flowing reach experiences moderate or more significant erosion over almost half (48.4%, 79.88 miles) of its length. The same table shows that 17.1% (28.30 miles) of the riverbanks have been rip-rapped. The total length of both banks combined in this northern reach is 165.12 miles.

Additional maps were prepared by Field in 2005 showing riverbank characteristics and erosion. Figure 10 (after Field Geology Services, 2005) shows a portion of this free-flowing reach with the various aspects related to channel characteristics and stability or erosion. Appendix B presents other maps prepared by Field showing the riverbank conditions in this free-flowing reach.



Figure 10. Example of Riverbank Characteristics – Northern, Free-Flowing Reach

4.2 Connecticut River Impoundments

4.2.1 Riverbank Erosion – Bellows Falls Impoundment

In addition to erosion sites documented by the USACE (1979) that included the Bellows Falls reach, a bank inspection was conducted in 1991 by the New England Power Company (included in this report as Appendix C). More recently, some erosion sites were identified and photographed in 1997 and again in 2008 by S&A. The location of the erosion sites are shown in Figure 11. An example comparing erosion from 1997 to 2008 is presented in Figure 12. As this example shows, the extent of erosion is similar and has continued over this 11-year time period (see Appendix D for a comparison of photos of erosion sites from 1997 to 2008 in the Bellows Falls Impoundment). The various sites where erosion was documented in 1997 were still eroding in 2008. While the full extent of erosion is not known in this impoundment in terms of mileage or percentage, geo-referenced video tapes were made of much of this impoundment that document the conditions as of 2008.



Figure 11a. Erosion Sites – Bellows Falls Impoundment, 1997



Figure 11b. Erosion Sites – Bellows Falls Impoundment, 1997



Figure 11c. Erosion Sites – Bellows Falls Impoundment, 1997

Bellows Falls Pool - Location 8



1997



2008

Figure 12. Riverbank erosion comparison, Bellows Falls Impoundment – Location 8 $% \left({{{\rm{B}}} \right) = 0} \right)$

4.2.2 Riverbank Erosion – Vernon Impoundment

Similar to the Bellows Falls Impoundment, erosion sites along the Vernon Impoundment were also photographed in 1997 and again in 2008. The locations of the erosion sites and images of the sites are shown in Figure 13. Figure 14 presents a comparison of erosion at a location in the Vernon Impoundment in 1997 and 2008, and shows that there are similar erosion and riverbank characteristics over this decade (see Appendix E for a comparison of photos of erosion sites from 1997 to 2008 in the Vernon Impoundment). The various sites that had documented erosion in 1997 were still eroding in 2008. While no evaluation of the extent or percentage of riverbanks experiencing erosion is available, geo-referenced video tapes were taken to document riverbank conditions for this reach of river in 2008.

As listed in available references, the power company that was operating the Vernon Station during the 1950s documented erosion in the Vernon Impoundment on a periodic basis. The 1954 document discusses and shows about 50 erosion sites that were photographed. Apparently, they were monitoring erosion sites along the Vernon Impoundment over time and documenting them by noting changes and taking photographs. Figure 15 presents an example of an erosion site taken by the Connecticut River Power Company in 1954. Other examples are found in Appendix F. The existence of this document shows that erosion has been an issue of concern for over half a century.



Figure 15. Erosion in Vernon Pool, 1954





Figure 13b. Erosion Sites – Vernon Impoundment, 1997

Vernon Pool – Location I







4.2.3 Riverbank Erosion – Turners Falls Impoundment

Riverbank erosion in the Turners Falls Impoundment has also been studied and monitored for several decades. In 1998 an Erosion Control Plan (Simons & Associates, 1998) was developed for the Turners Falls Impoundment which mapped riverbank features and characteristics to select 20 sites to be considered for stabilization. As part of the Federal Energy Regulatory Commission (FERC) license for the Northfield Mountain Pumped Storage Project and Turners Falls Hydroelectric Project, the Licensee is required to conduct full river reconnaissance (FRR) surveys of the Turners Falls Impoundment every 3-5 years to document erosion areas and the results of stabilization measures that have been implemented. An FRR was conducted in 2008 (Simons & Associates, 2009). The report provides documentation of the distribution of riverbank features and characteristics in the form of detailed maps of riverbank sediment types, slope, height, vegetation, severity and type of erosion. In addition to the maps showing the detailed breakdown of features and characteristics, summary maps were developed that delineated riverbank conditions into 8 broad groups of combination of features and characteristics related to stability or erosion (Table 2). An example of the results of the 2008 FRR (Simons & Associates, 2009) is shown in Figure 16. Segments of riverbank marked with hot pink, red, orange, and yellow are experiencing the most significant erosion while segments of river marked in blues, brown, green, and black exhibit stability. Appendix G presents the summary maps for the 2008 FRR. Detailed maps of all features and characteristics are found in the 2008 FRR report (Simons & Associates, 2009).

The score or group of characteristics in the 2008 Turners Falls Impoundment reconnaissance is explained in the following table.

Group/Score	Characteristics
1	Extensive mass wasting (erosion)
2	Some mass wasting (erosion)
3	None to sparse upper bank vegetation
4	Moderate to heavy vegetation with steep to overhanging
	banks
5	Moderate to heavy vegetation with moderate upper bank
	slope and moderate to steep lower banks
6	Moderate to heavy vegetation with moderate upper bank
	slope and flat lower bank slope
7	Moderate to heavy vegetation with flat upper bank slope
	and flat lower bank slope
8	Rock

Table 3. 2008 FRR Summary Groups

Results of the 2008 FRR showed that 83.3% of the riverbanks showed little to no erosion, while some erosion was found for 16.1% of the reach and extensive erosion was found in 0.6% of the Turners Falls Impoundment.

Riverbank Score - Section 2



Figure 16. Example of Full River Reconnaissance Map – Turners Falls Impoundment

Photographs are available at several erosion sites in the Turners Falls Impoundment taken before and after riverbank stabilization projects that have occurred with implementation of the ECP. Many of the erosion sites identified in the ECP have been stabilized by a range of measures including placement of rock at the toe of the slope, coir logs, placement of large woody debris, various fabrics, and planting of vegetation including riparian and aquatic. Some re-shaping of riverbanks has also been conducted at some sites. An example of the transformation from an unstable, eroding riverbank to a stabilized riverbank is shown in Figure 17. As shown by this comparison of photos from before 2004 to 2008, the eroding bank has been stabilized by placing relatively small rock at the toe of the slope and planting vegetation above the rock on the formerly eroded bank. The 2008 photo shows the transformation from erosion to stabilization efforts in the Turners Falls Impoundment. From the commencement of implementation of the ECP to the present, approximately 14,000 feet of riverbank have been stabilized in the Turners Falls Impoundment.

In addition to stabilization of erosion sites, natural stabilization processes as a result of increasing expansion of vegetation has been observed over the period from 1998 to 2008. Areas of increased vegetation on upper riverbanks – both relative to density as well as height have been observed over this time period. Some areas of dense aquatic vegetation on lower riverbanks have also been observed. An example of natural stabilization processes is shown in Figure 18 where ongoing erosion processes are evident in 1996 with numerous trees that have fallen down, other trees tipping and on the verge of falling along with fresh erosion scars. This area of erosion is located immediately downstream of Vernon Dam on the east side of the Connecticut River. In 2008, there are no recently fallen trees, very few tipping trees, and an increased band of trees and other vegetation is growing in the transition area between the steep upper bank and the flatter lower bank where beach formation is evident. Less fresh erosion scarring can be seen. Other examples of these natural stabilization processes through increasing vegetation expansion in the Turners Falls Impoundment are shown in Appendix I. Additional expansion of vegetation was also noted during a field trip observing riverbank conditions taken in the fall of 2009.



Site 6 – Skalski, prior to 2004



Site 6 – Skalski, 2008 (from Maintenance Inspection Report)

Figure 17. Comparison of Skalski Site pre 2004 to 2008



1996 - Eddy-induced erosion downstream of Vernon Dam



2008 – Eddy-induced erosion downstream of Vernon Dam

Figure 18. Natural stabilization processes 1996-2008 downstream of Vernon Dam

4.2.4 Riverbank Erosion – Holyoke Impoundment

Erosion sites identified in the Holyoke Impoundment were photographed in 1997 and again in 2008. The locations of the erosion sites are shown in Figure 19. An example of riverbank erosion in the Holyoke Impoundment from 1997 to 2008 is shown in Figure 20. The extent and severity of erosion is similar and has continued over this 11-year time period (see Appendix J for a comparison of photos of the various erosion sites from 1997 to 2008 in the Holyoke Impoundment). The various sites eroding in 1997 were still eroding in 2008. While no evaluation of the extent or percentage of riverbanks experiencing erosion is available, geo-referenced video tapes were taken to document riverbank conditions for this reach of river in 2008.


Figure 19a. Location of Erosion Sites - Holyoke Impoundment, 1997



Figure 19b. Location of Erosion Sites – Holyoke Impoundment, 1997



Figure 19c. Location of Erosion Sites – Holyoke Impoundment, 1997

Holyoke Pool – Location D









5. Discussion of Erosion along the Connecticut River

Information from a variety of sources was compiled regarding riverbank erosion along the Connecticut River. Available information covers most of the Connecticut River including from many of the low-head hydropower impoundments including Bellows Falls, Vernon, Turners Falls, and Holyoke Impoundments as well as from the longest free-flowing reach from Pittsburg to Gilman. The reaches not covered by the available information include: a) the uppermost reach from its origin to Canaan Dam, b) the seasonally fluctuated storage reservoirs (Comerford and Moore Reservoirs), and from Holyoke Dam to Long Island Sound. Information from approximately 240 miles of river was obtained representing 59% of the overall river length. A wide range of flow/operation conditions occur in these reaches for which riverbank erosion information was obtained.

Riverbank erosion occurs in the reaches described above whether free-flowing or impounded for hydropower operations. The ubiquitous nature of riverbank erosion in the Connecticut River provides yet another example of the dynamic nature of rivers explained in the scientific literature. The scientific literature (Leopold, et al, 1964) states that even under ideal conditions in the so-called "equilibrium" channel in real-world conditions:

In actuality a natural channel not only carries sediment but migrates laterally by erosion of one bank, maintaining on the average a constant channel cross section by deposition at the opposite bank. In this case the condition of no bank erosion is replaced by an equilibrium between erosion and deposition. The form of the cross section is "stable," meaning constant, but position of the channel is not.

Furthermore, Schumm (1977) states that,

Frequently environmentalists, river engineers, and others involved in navigation and flood control consider that a river should be unchanging in shape, dimensions and pattern. This would be very convenient. However, an alluvial river generally is changing its position as a consequence of hydraulic forces acting on its bed and banks.

Archaeologists have provided clear evidence that the lateral shift of channels is completely natural and to be expected.

In summary, archaeological, botanical, geological, and geomorphic evidence supports the conclusion that most rivers are subject to constant changes as a normal part of their morphological evolution.

The fact that erosion is found in all reaches and all conditions encountered in the alluvial sections of the Connecticut River is to be expected as a natural part of alluvial channel geomorphology.

As demonstrated by the available information, riverbank erosion occurs in all reaches of the Connecticut River. Beyond this basic fact, there are differences in hydraulics and hydrology – some reaches are subject to peaking hydropower operations and others not that provide insight into the potential effect on riverbank erosion. The Connecticut River is separated into three types of reaches including: a free-flowing reach from Pittsburg to Gilman; low-head hydropower impoundments that operate in both run of river and peaking power modes (Wilder, Bellows Falls, Vernon, and Holyoke²); and low-head hydropower impoundment that operates in run of river and peaking power modes plus pumped-storage mode (Turners Falls). The following points can be made based on the available information and observation of these three types of reaches.

The free-flowing reach (Pittsburg to Gilman):

- This reach responds to a relatively natural seasonal hydrograph and associated natural water level variations.
- The velocity of flow in this free-flowing reach is generally higher than impounded reaches. The channel bed slope of the river is generally steeper resulting in increased velocities.
- Based on Field's (2004) evaluation, the primary causes of erosion are: "1) channelization; 2) land clearance and other human land use in tributary watersheds; 3) continuing adjustments to deglaciation; 4) agricultural practices in the riparian zone; 5) dams; and 6) reforestation of hillslopes cleared in the 18th and 19th Century."
- Significant riverbank stabilization and erosion protection has been constructed with 17.1% of the riverbanks being rip-rapped.
- Erosion in some unprotected areas was attributed to erosion protection in adjacent segments of riverbank.
- Observations indicate boat use in this free-flowing reach is predominantly smaller boats (fishing, duck hunting) rather than larger boats that typically are used in impounded reaches.
- Field's (2004) study showed that 25.8% of the riverbanks were eroding, 22.6% were moderately eroding for a total of 48.4% of the riverbanks experiencing erosion.

The low-head hydropower reaches with run of river/peaking operation (Wilder, Bellows Falls, Vernon, and Holyoke):

- These low-head dams create relatively narrow impoundments with decreased velocities through a range of flows.
- These hydropower plants generally operate either as run-of-river, when flows exceed the hydraulic generating capacity of the project; or as a peaking project, when flows are within the hydraulic generating capacity of the project. Peaking power operations result in fluctuations in water level in the impoundment upstream of the dam and fluctuations in flow and water level in the impoundment

² While Holyoke is technically a daily cycle hydropower operation, the storage capacity of the upstream reservoir is so limited that it essentially operates as a run-of-river facility.

downstream of the dam. Multiple boat launches exist along these impoundments and motorized boats resulting in waves are used on these impoundments.

• While some localized riverbank stabilization exists, almost all erosion sites identified in 1997 appeared to be in essentially the same condition in 2008 indicating that these sites of significant erosion continue to experience erosion.

Turners Falls Impoundment with low-head hydropower impoundment operating in both run-of-river and peaking power mode plus pumped storage:

- This low-head dam creates a relatively narrow impoundment that generally decreases velocities through a range of flows. The French King Gorge (a narrow, rocky gorge) located a relatively short distance upstream of the Turners Falls Dam creates a pinch-point (natural hydraulic control) such that hydraulic conditions at moderate to high flows in the river upstream of the gorge are controlled by the natural resistance to flow and restriction of the flow through this narrow gorge. Thus, this reach operates as an impoundment at low to moderate flows, but from moderate to high flows; the reach upstream of French King Gorge operates as a river being controlled by this natural constriction.
- Turners Falls Hydroelectric Project operates as a run-of-river project when flow exceeds the facility's turbine capacity and generally in a peaking mode when flows are below the turbine capacity. Hydroelectric operations at the upstream end of the impoundment follow the same modes (peaking when the flow is less than hydraulic generating capacity and run-of-river when the flow is greater than the hydraulic capacity) due to operations at Vernon Dam. Additionally, the Northfield Mountain Project operates as a peaking project, typically generating during the day and pumping water to the upper reservoir at night. Water level fluctuations in the Turners Falls Impoundment are the result of operations at Vernon which propagate flow and water level fluctuations through the impoundment as well as due to operations at the Turners Falls and Northfield Mountain Projects. These operations and analyses of hourly data are found in Simons & Associates, 2012. Multiple boat launches exist along the impoundment and powerboats are used on this impoundment.
- Many erosion sites identified in the 1990s have been stabilized through implementation of the ECP.

The fact that riverbank erosion exists in a variety of conditions (free-flowing and impounded) along the Connecticut River with different operations (run of river/peaking power, pumped storage) and responses provides an opportunity to learn from this range of conditions and differences or similarities between the various reaches. Various points can be made based on a comparison of these reaches of river.

• The greatest percentage (48.4%) of erosion occurs in the northern unimpounded, free-flowing reach from Pittsburg to Gilman. This is consistent with the 1979 USACE analysis where a theoretical comparison of hydraulic forces associated with various causes of erosion showed that *"the presence of pools reduces bank erosion on the order of 34 percent compared to the natural river,"* because of

reduced velocities and shear stresses which outweighs increased forces due to pool fluctuations in the analysis of forces.

- The least percentage (16.7%) of erosion is found in the Turners Falls Impoundment (with run of river/peaking power and pumped storage hydro operations). This is likely due to somewhat decreased riverine forces as a result of a lower natural longitudinal slope and impoundment, implementation of the ECP, and some natural stabilization processes observed in this reach.
- Even without the 14,000 feet of stabilization through the ECP in the Turners Falls Impoundment which represents about 7% of the length of both sides of the river, the percentage of erosion in this reach would be much less (at 16.7 +7 = 23.7%, 10.44 miles) than the percentage (48.4%,) of erosion documented in the northern, free-flowing reach (especially considering that 17.1% [28.3 miles] of the northern reach has been rip-rapped and 10.5 %, [4.91 miles] of the Turners Falls Impoundment has been rip-rapped).
- The 1979 study showed 19.84 miles of eroded bank in the Wilder Impoundment, 4.05 miles in Bellow Falls, 9.91 miles in Vernon, and 3.13 miles in Turners Falls. While no percentage or length information is available of current erosion sites in the low-head hydropower impoundments (Wilder, Bellows Falls, Vernon, and Holyoke) as of 2008, the upstream impoundments had the greatest number of erosion sites based on the 1979 study (which did not include the northern, unimpounded reach). Based on the 2008 inspection in Bellows Falls, Vernon, and Holyoke all but one of 23 erosion sites identified in 1997 were in essentially the same eroding state in 2008.

As shown in Figure 21 (from the USACE study, 1979), water level fluctuations are largest in the Turners Falls Impoundment due to the pumped storage facility in addition to the run of river/peaking power operation compared to other hydropower impoundments. More recent data (9/1/2012 - 10/23/2012) from USGS stations at Dalton, West Lebanon, North Walpole, and at Montague City present the gage height hydrographs. The Dalton gage (Figure 22) is in a free-flowing reach upstream of the Wilder Impoundment, West Lebanon (Figure 23) is located in the Bellows Falls Impoundment a short distance downstream of the Wilder Dam, North Walpole (Figure 24) is in the Vernon Impoundment a short distance downstream of the Bellows Falls Dam, and Montague City (Figure 25) is downstream of the Turners Falls Dam in the Holvoke Impoundment. Dalton represents a free-flowing reach of river while the other gages show the typical fluctuations associated with peaking power operations in their respective impoundments. Fluctuations are in the 3 to 4 foot range at West Lebanon (Bellows Falls Impoundment – also affected by inflow from Wilder), predominantly 3 feet at North Walpole (Vernon Impoundment – also affected by inflow from Bellows Falls), and 4 to 5 feet in the Holyoke Impoundment - also affected by releases from Turners Falls. These recent data show that fluctuations are approximately one foot larger in amplitude downstream of the Turners Falls Impoundment (in the Holyoke Impoundment) compared to fluctuations in upstream impoundments, which appears to be a smaller increase in fluctuations associated with Turners Falls as also demonstrated in Figures 26 through 28. These figures compare water level fluctuations that result from peaking power operations due to Vernon at the upstream end of the Turners Falls Impoundment to fluctuations at the Northfield Mountain Tailrace. Water level fluctuations at the upstream end of the Turners Falls Impoundment are due to peaking power operations at Vernon Dam and typically range from about 2 to 4 feet in amplitude in the examples from July 1997 and December 2000. At the Northfield Mountain Tailrace, water level fluctuations ranged from about 2 to 4 feet in July 1997 and approximately 2 to 5 feet in December 2000. Thus, water level fluctuations in the Turners Falls Impoundment are similar to or up to about 1 foot larger in amplitude compared to fluctuations in other impoundments.



Figure 9. Pool stage compared to time at the four study reaches. Figure 21. Water level fluctuations at four hydropower impoundments



Figure 22. Gage height near Dalton, NH 9/1/2012-10/23/2012



Figure 23. Gage height at West Lebanon, NH 9/1/2012-10/23/2012







Figure 25. Gage height at Montague City, MA 9/1/2012-10/23/2012



Figure 26. Water Level Fluctuations in Turners Falls Impoundment, 7/11-16/1997



Figure 27. Water level fluctuations in upper Turners Falls Impoundment due to operations at Vernon, December 2000



Figure 28. Water level fluctuations at Northfield Mountain Tailrace, December 2000

The greatest extent of erosion is found in the reach of river that has the greatest extent of stabilization and minimal to no water level fluctuations due to hydroelectric operations. Within reaches that are impounded for hydroelectric operations, the impoundment with somewhat larger water level fluctuations experiences the least erosion. Comparison of erosion with respect to water level fluctuations suggests that the water level fluctuations do not play a significant role in the riverbank erosion process.

Stabilization efforts have been conducted in various reaches of the Connecticut River. While stabilization projects can reduce the severity and extent of erosion, riverbank erosion resulting in channel change and lateral shifting is a natural geomorphic process as discussed in the scientific literature. A benchmark of natural alluvial river processes can be seen in rivers located in national parks where hydropower, powerboats, agriculture, and riverbank stabilization is not typically allowed. Riverbank erosion in rivers located in national parks is readily evident as shown in the example photographs below (Figures 29 and 30). Appendix K presents additional examples of significant riverbank erosion occurring in national parks. The fact that erosion of rivers in areas without significant human influence clearly demonstrates the natural dynamics of alluvial rivers as previously explained in the scientific literature.



Figure 29. Yellowstone River – Yellowstone National Park



Figure 30. Middle Fork of the Flathead River – Glacier National Park

Given the dynamic nature of alluvial rivers, complete control of erosion is impossible without taking extreme measures resulting in an unnatural channel and would contradict natural geomorphic processes. In analyzing the Connecticut River, Field (2007) commented on the nature of riverbank sediment found in the Turners Falls Impoundment reach of the Connecticut River.

Most of the riverbank sediments in the Turners Falls Pool are naturally susceptible to erosion given their noncohesiveness and fine-grained texture.

Observation of other reaches of the Connecticut River indicates similar erodible sediments consistent with deposition in old Lake Hitchcock that extended through much of the length of the river.

Furthermore, Field stated (2007),

"Erosion is a naturally occurring phenomenon that is present even on rivers in equilibrium where erosion is offset by an equal amount of deposition in adjacent areas.

Field (2004) in evaluating the best approach to *"help preserve surrounding farmland"* he discussed ill-advised erosion protection and the need to allow some degree of erosion before the river will shape itself into a more stable pattern.

Completely stopping the erosion with riprap or other bank armoring techniques, however, will lock the channel instabilities in place and potentially transfer the erosion processes further downstream.

He then advises to "*identify how far the erosion will extend*" stating that even an aggressive erosion protection technique "*riprap to fail and allow the erosion to continue*" and allow the river to erode by simply planting a buffer zone of riparian vegetation until "*reaching this more natural configuration*." He also supports the approach to "*acquire conservation easements in order to reduce human conflicts*."

Field (2007) discussed a potential problem riverbank stabilization projects noting that, *"both riprap and bioengineering projects, could lead to increased erosion elsewhere."*

This material from Field recommending not to "fix" every erosion issue along the Connecticut River is consistent with the approach taken by the Vermont Agency of Natural Resources (VANR). Natural rivers, even those in "equilibrium," are expected to experience changes in position through processes of riverbank erosion and lateral shifting. Artificially constraining the river's position via erosion protection or stabilization projects can adversely affect riverbanks upstream, downstream or across the river and it raises the question as to the role, objective, or extent of such stabilization projects. The VANR suggested an alternative approach in their 2007 "River Corridor

Planning Guide to Identify and Develop River Corridor Protection and Restoration Projects." Their river corridor concept is based on the concept of dynamic equilibrium of rivers where "Streams in equilibrium may still erode their banks, migrate over time across their valleys, and periodically experience small-scale lateral and/or vertical adjustments." They advocate "Defining and protecting the meander belt width corridor that will accommodate equilibrium conditions may be the most important aspect in any river restoration project." In other words, enough room needs to be allowed for a river to move and adjust within the concept of dynamic equilibrium. Or, as stated by Sharon Francis, (Executive Director - Connecticut River Joint Commissions), "A wise public must give the river room to be a river." This concept is reinforced by the VANR when they state that, "In nearly every Vermont watershed, there will be a need to reduce or remove constraints to the lateral adjustment of the stream channel." In other words, give the river room to be a river. They explain further,

"Restoration projects have traditionally attempted to resolve conflicts by 'fixing,' and often re-fixing, the location of the channel. Inevitably, when the restoration planner ignores the channel evolution process, the energy of a large flood brings another round of traditional channel works perpetuating the conflicts at the restoration site or exacerbating the conflicts somewhere downstream."

This concept has been developed and utilized in other states including Montana, New Mexico, and Ohio and was studied by the Federal Emergency Management Agency (FEMA), 1999, "Riverine Erosion Hazard Areas - Mapping Feasibility Study,"

While riverbank stabilization and erosion protection can be successful in reducing erosion, examples of the adverse consequences of such activities exist on the Connecticut River. The fact that the VANR and the CRJC (as well as other states and agencies) have expressed concern over constraining rivers beyond their natural dynamic nature to the extent that documents and regulations have been written to accommodate lateral migration and channel shifting (which necessarily means allowing some degree of riverbank erosion). The fact that rivers cannot be completely controlled must be considered carefully in future evaluation and planning for such projects.

6. Conclusions

Some erosion of riverbanks is occurring along the length of the Connecticut River, both in free-flowing reaches and within reaches impounded by dams. Erosion has been occurring along the Connecticut River over a long period of time, likely since the draining of Lake Hitchcock and on to the present; and for as long as observations have been documented, as shown in available material as early as a half-century ago in the 1950s. The fact that some erosion is occurring is consistent with the fact that rivers are dynamic; meaning that they experience lateral migration, and continually change in dimension, shape, and pattern. Other than reaches consisting of bedrock or other materials and characteristics that are resistant to erosion, or have been stabilized; erosion or the potential for erosion is ubiquitous throughout the various reaches or segments of the Connecticut River. Erosion exists in all of the impoundments as well as in freeflowing reaches of the river.

Despite the fact that there has been similar extent of erosion control or riverbank stabilization in the northern, free-flowing reach of the Connecticut River compared to the Turners Falls Impoundment (17.1% rip-rapped for the northern, free-flowing reach vs. 10.5% rip-rapped plus 7% bio-engineered stabilization through the ECP for the Turners Falls Impoundment); the reported percentage of eroding river in the northern, free-flowing reach is approximately triple (48.4% to 16.7%) compared to the Turners Falls Impoundment. The fact that erosion is greater in the free-flowing reach compared to an impounded reach is consistent with the analysis presented in the 1979 USACE report because an impounded reach generally experiences reduced velocities and reduced shear stresses which outweighed impoundment fluctuations in causing riverbank erosion.

While no recent quantitative assessment of the riverbanks in the Bellows Falls, Vernon or Holyoke Impoundments is available at this time; individual erosion sites found in 1997 were re-visited and photographed in 2008. From a qualitative perspective, based on the comparison of photos of erosion sites from 1997 to 2008, in these three other impoundments all but one of the erosion sites in 1997 continues to experience virtually the same degree of erosion in 2008. Many of these erosion sites are significant both in size and severity. In contrast, most of the severely eroded sites in the Turners Falls Impoundment found in 1997 have been stabilized by 2011 through implementation of the ECP. Some natural stabilization processes of increased upper bank vegetation and areas of dense low bank aquatic vegetation have also been observed in the Turners Falls Impoundment.

Despite somewhat larger pool fluctuations as a result of the combination of fluctuating discharges from upstream releases at Vernon, fluctuations in water level due to peaking power operations at the Turners Falls Dam (Cabot Station), and water level fluctuations due to peaking power operations due to the pumped-storage facility (Northfield Mountain); these fluctuations have not resulted in greater erosion in the Turners Falls Impoundment compared to other reaches along the Connecticut River. This may be because impoundment fluctuations do not play a large role in eroding banks as suggested by the 1979 USACE study which attributed 15-18% of the cause of erosion to impoundment fluctuations, the buffering effect of impoundments which tend to slow river velocities, natural stabilization, and/or stabilization efforts at most of the severely eroded sites through implementation of the ECP. Whatever the reason (or combination of reasons), there is no evidence to support the argument that impoundment fluctuations resulting from a combination of hydropower projects cause greater erosion in the Turners Falls Impoundment because riverbank erosion is less severe and/or less extensive compared to any other reach of the Connecticut River.

7. References

Connecticut River Power Company, 1954 "Observation of Erosion on Banks of the Connecticut River Bellows Falls to Vernon September 2-3, 1954,"

Federal Emergency Management Agency, "Riverine Erosion Hazard Areas – Mapping Feasibility Study," 1999

Field Geology Services, 2004, "Fluvial Geomorphology Assessment of the Northern Connecticut River, Vermont and New Hampshire"

Field Geology Services, 2007, "Fluvial Geomorphology Study of the Turners Falls Pool on the Connecticut River between Turners Falls, MA and Vernon, VT"

Leopold, L.B., M.G. Wolman and J.P. Miller, 1964, <u>Fluvial Processes in</u> <u>Geomorphology</u>, W.H. Freeman and Company

Rittenour, T. M., 1999, "Drainage History of Glacial Lake Hitchcock, Northeastern USA," unpublished MS thesis, University of Massachusetts

Schumm, S., 1977, Fluvial Processes in Geomorphology, John Wiley & Sons

Simons & Associates, 1992, "Analysis of Bank Erosion at the Skitchewaug Site in the Bellows Falls Pool of the Connecticut River"

Simons & Associates, 1996, "Discussion of Erosion at Vernon Station"

Simons & Associates, 1998, "Erosion Control Plan for the Turners Falls Pool of the Connecticut River"

Simons & Associates, 2008, "Full River Reconnaissance – 2008 Turners Falls Pool, Connecticut River"

Simons, Li & Associates, 1983, "Erosion Study to Determine Boundaries for Adjacent Development – Calabacillas Arroyo, Bernalillo County, New Mexico," prepared for the Albuquerque Metropolitan Arroyo and Flood Control Authority

Simons, D.B. and F. Senturk, 1991, <u>Sediment Transport Technology – Water and</u> <u>Sediment Dynamics</u>, Water Resources Publications

United States Army Corps of Engineers, 1979, "Connecticut River Streambank Erosion Study Massachusetts, New Hampshire and Vermont"

Vermont Agency of Natural Resources (Mike Kline and Kari Dolan, River Management Program), 2008, "Fluvial Geomorphic-Based Methodology to Reduce Flood Hazards and Protect Water Quality"

Vermont Agency of Natural Resources, "Mitigating Flood-Related Fluvial Erosion Hazards (FEH) Using River Corridor Protection, Fact Sheet"

APPENDIX A

LOCATIONS OF EROSION SITES IN THE STUDY REACH











1

A-6







A-9





A-11














A-18



Appendix B – Erosion and Bank Composition Maps – Northern Connecticut River (after, Field Geology Services (2005)














































































Appendix C – Bellows Falls Pond Bank Inspection, 1991

BELLOWS FALLS POND BANK INSPECTION 30 May 1991

GENERAL

> 1. 2.

The Bellows Falls Pond banks were inspected by boat on 30 May 1991. The inspection party consisted of Bernard Hinds - Bellows Falls, John Huysentruyt - Lebanon, and Christopher Kane and Armand Millette - Westborough, Civil Engineering.

The boat was launched from the ramp on the New Hampshire side of the river, 0.3 miles above Windsor Bridge. The bridge gage reading was Elevation 116.45 and the boat became moored on shoals just downstream of the bridge. <u>Note</u>: The gage <u>must</u> read Elevation 116.5 or higher to negotiate this section of the river. The deepest channel hugs the Vermont shore. The river flow at Bellows Falls dam averaged 6,400 CFS.

Generally, the pond banks have continued to be active since the 1977 inspection. The following properties continue to cut back and be active as previously noted:

	<u>River Mile</u>	Original Owner	_File No.	Riverbank
1.	24.3 - 23.7	L. M. Baker	BF-303	New Hampshire
2.	21.0	W. J. Wilgus	BF-147	Vermont
3.	13.8	Whitmore	BF-225	New Hampshire
4.	12.6 - 12.0	V. W. Tallman	BF-229	New Hampshire
5.	11.5 - 11.0	Vital Blais	BF-86	Vermont
6.	5.8 - 5.7	Kenyon	BF-73	Vermont
7.	5.7 - 5.3	New England Power Co.	BF-68	Vermont
8.	4.9 - 4.5	Stearns-Piper	BF-184,185	New Hampshire
9.	4.5 - 4.2	New England Power Co.	BF-182,183	New Hampshire
10.	2.2 - 1.9	Rutland Railroad	BF-56	Vermont
11.	1.3 - 1.2	New England Power Co.	BF-173b	New Hampshire
12.	1.2 - 0.8	Cray Oil Company	BF-172b	New Hampshire

At River Miles 22.4 and 22.1, a large outwash was observed in 1976 at each location on the Vermont side with steep sided gullies back from the river several hundred feet. The 20 May 1976 inspection of both locations between Route 5 and the river indicates each area is the result of uncontrolled drainage from an intermittent sand and gravel operation (Mile 22.4) and a 10-acre cornfield (Mile 22.1). This erosion problem is on the following properties:

<u>River Mile</u>	Original Owner	File No.	Riverbank
22.4	A. G. Westney	BF-250	Vermont
22.1	F. D. Whitcomb	BF-149	Vermont

New England Power Company has flowage rights on both properties. The Whitcomb property shows evidence to control the erosion because numerous

ID 6269	-1-	AJM/CGK:	May	1991
---------	-----	----------	-----	------

trees are cut and laid onto the gully slopes along with stones dumped at the start of the gully. There is no apparent effort on the Westney property to stop the erosion. Both areas should be checked periodically from Route 5 for the record. These areas appear stabilized in 1984 and 1991.

Photographs were taken where conditions appeared to have changed and were spotted at many locations of previous inspections for comparison purposes.

INSPECTION NOTES

INSPECTION NOTES	
<u>Mile 26.4 to 25.8</u> NH	Railroad Bridge to Foot of Chace Island. New Nampshire The Weld property slides are inactive along this 1.500' long bank with some healing evident. Gravel shoals are building up in the river upstream of Chace Island. [See Picture A-1] Shoals also building on upstream bank of Chace Island. [See Picture A-2]
<u>Mile 25.7 to 25.5</u> VI	"Kennedy Farm". Vermont This 800' long section of bank is inactive, weed covered, and shows signs of healing. A 50' long by 20' high slide at the upstream property line, noted in 1977, is still healing.
Mile 25.5 to 24.2 VT	BF-253, A. B. McClary, Vermont This section is slightly active with gravel build-up along banking, with 8 dead elms down at Mile 24.2.
<u>Mile 25.0</u> NH	G. 8. Mood. New Hampshire This section appears inactive. There is a dead eim standing at the top of slope and another down on the slope.
<u>Mile 24.6</u> NH	Bf-301. U. A. & M. A. Stimpson. Rew Hampshire This 75' long slide continues to be active and raw since 1964. Trees are sliding on the slope and in the water. Outwash and gravel build-up is occurring from the stream at the downstream property line.

ID 6269

-2-

Mile 24.3 to 23.7 NH	BF-303, 304, & 305, Baker, Chadbourne, & Ballock New Hamoshire This 2,000° long by 30° high bank is still active along the Baker property and moderately active in the downstream half. This section shows the active conditions with trees down on the bank and slope sods. [See Pictures A-3 & A-4] The undercutting continues active on the Chadbourne property with poplars undercut and trees down at the river's edge. At the Chadbourne-Ballock property line, the lower bank continues to be active for 500°. Clumps of brush and undercut trees continue to slide on the slope and shoals are evident near shore.	
<u>Wile 23.9 to 23.5</u> VT	BE-252. Austin's Greenhouses. Inc. Vermont A 100' long by 40' high section is now active with trees down on slope. [See Picture A-5] At the Windsor-Weathersfield town line, there are two 50' long by 30' high slides which remain stabilized by dumped gravel and rip-rap. [See Picture A-6] Rock placed on the slope in 1984 is Keeping bank stabilized. [See Pictures A-7 & A-8]	
<u>Hile 23.6</u> NH	Philip Pederson. New Hampshire Previously noted trees remain on the slope for protection.	
Mile 23.5 NH	BF-277. Leonard R. Haubrich. New Hamoshire A 100' long by 20' high section with trees leaning and down is stabilizing with moderate grass and brush growth. [See Picture A-9]	
Mile 23.3 to 22.8 VT	BF-252. Vinton H. Parker. Vermont At Mile 23.0 the 1984 report noted 2 shoals connected with the downstream shoal approximately 1,000' long. It appears that the shoals have been separated. [See Picture A-10] A 300' long by 20' high slide is now active at Mile 22.9 with 6 birch trees down. [See Picture A-12]	
<u>Wile 23.0</u> NH	BF-274, Sadie & Fletcher Donoghue. New Hampshire A high slide active in 1984 has since had trees, stumps, and brush cover dumped on the slope stabilizing activity and allowing healing. [See Picture A-11]	
Mile 22.8 NH	BF-275. Stephen R. Breck, New Hampshire This slide continues to be active with trees leaning and sods on the bank.	
Mile 22.7 VT	BE-251, Clarence H. Martin, Vermont The campsite prosion remains inactive with small stones on bank. [See Picture A-13]	
10 6269	-3- AJM/CGK: May 1991	

Mile 22.4 VT	BF-250. Albert G. Westney. Vermont A large 40' deep gully, previously noted, created a 200' long outwash along the shoreline. A land inspection on 20 May 1975 revealed this gully resulted from an uncontrolled drainage pattern through an intermittent sand and gravel operation on this property and a trash landfill operation beyond the gravel excavation. This area has stabilized since 1977.	
Mile 22.1 VT	BF-149, Frank D. Whitcomb. Vermont The large gully noted in 1974 has stabilized. This gully extends about 500 feet back from the river and is a result of drainage from a large confield between the tree line and Route 5. [Picture A-14] shows the gully area.	
Mile 22.1 to 21.8 NH	<u>BF-270, Hugh and Mary E. Deming, New Hampshire</u> The downstream area active in 1984 is now inactive and healing with moderate brush cover and tree growth. ISee Picture B-1]	
Mile 21.7 VT	BF-252, Harlan L. Whipple, Vermont This low silt bank just upstream of the new Ascutney Bridge is still healing since 1977.	
Mile 21.6 WH	BF-269, Roy D. Hunter, New Hampshire There are 3 trees down and in water at the Sugar River Confluence, [See Picture B-2]	
Mile 21.5	Connecticut River Upstream shot of Ascutney Bridge. [See Picture 8-3]	
Mile 21.5 VT	BF-147. Leonard M. Wilgus. Vermont A scoured area with outwash noted in 1977 is now inactive and healing except where a dead tree is down in the river. [See Picture B-4]	
Mile 2 <u>],5 to 20,9</u> NH	BF-269, Roy D. Hunter. New Hampshire This long low meadow bank, rated in 1977 as active for 500 feet of the upstream end, is now healing and the remaining downstream portion is weed covered and inactive.	
Mile 21.0 VT	BF-147. M. J. Milgus, Vermont This 200' long by 40' high section abotting Wilgus State Park is now active with slides at top of slope approximately 15' from high voltage tower. [See Pictures B-5 & B-71 The banking upstream is inactive where rip-rap has been placed. [See Picture B-6]	

ID 6269

-4-

N11e 20.5 to 20.5 NH	<u>BF-268. James Duncan Urham. New Hampshire</u> This area is now inactive with 3 trees laying on upstream bank and 2 large pines uprooted on downstream bank.
Mile 20.8 to 20.4 VT	BF-147. W. J. Wilgus. Vermont 200' long by 10" high section has had rip-rap placed on bank with a new boat ramp. [See Picture B-8] Downstream tank is slightly active with areas of scouring. [See Pictures B-9 & B-10]
Mile 20.7 to 19.7 VT	<u>BF-146. Horace C. Mayhew. Verment</u> The upstream end of this 15' high bank is active with trees leaning and sliding. There is weed cover on the downstream end. [See Picture B-11]
<u>Mile 19.7 to 19.5</u> VT	<u>BF-145. Fred W. Fullam. Vermont</u> This 12' high bank continues to be active with sods on the slope. There are several clumps of small trees down on the slope. A 30' high slide on the downstream end was rip-rapped in 1976 and appears stable.
Mile 19.5 to 19.2 NH	BF-267, Russell Jarvis, New Hampshire This 10" high bank is inactive and healing.
<u>Mile 19.5 to 19.0</u> VT	<u>BF-144. Clarence R. Randall. Vermont</u> This section is active with raw, undercut banks and many trees either undercut and down on the slope. At Mile 19.2 there is a house 20 feet from the top of slope. Trees on the slope have been cut since 1977 and the bank shows signs of healing. A yellow house, approximately 30 feet from the top of slope, and a write house is approximately 10 feet from the top of slope with a picket fence at the top of slope.
Mile 18.6 NH	BE-267. Russell Jarvis. New Hampshire This slide area continues active for 150' by 70' high with sliding trees on the slope and at the river's edge. [See Picture B-12]
<u>Mile 18,3</u> Vi	BF-141, W. Eugene Moore. Vermont This bank remains active with trees down on the slope. [See Picture B-13] Brush has been cut on the slope and fence posts are lying at the top of slope.
Mile 18.2 to 17.7 NH	<u>BF-266 and BF-265, Laura L. & J. Laban Ainsworth.</u> <u>New Mampshire</u> The upstream end of this section is active with trees leaning. [See Picture B-14] River silt fill has been dumped over the bank on the downstream section and is inactive.
ID 6269	-5- AJM/CGK: May 1997

- Mile 18.2 to 17.7
 BF-141. M. Eugene Moore. Vermont

 VT
 The old 15' high slide remains active with sods and trees down on the slope.
- Mile 17.8 Connecticut River Upstream shot of Island. [See Picture B-15]
- Mile 17.5 to 17.4
 BF-269. Martin Hougsrud. New Hampshire

 NH
 New asphalt boat ramp with rip-rapped banks on each side. (See Picture B-16) Drain 20' from river with dirt road 50' downstream. [See Picture B-17]
- Mile 17.3 to 17.2
 BF-139, Ben Johnson, Vermont

 VT
 Active bend in river with trees leaning in water. [See Picture B-181 Downstream more trees leaning in water, [See Picture 8-19]
- Mile 16.6 to 16.5
 BF-260. Drusilla Farwell. New Hampshire

 NH
 The wooded banks on each side of the channel are inactive and grassed over. At the upstream end of the channel, there are numerous leaning trees and heavy ice scars on tree trunks. The main stream side of Hubbard Island is raw with many trees down for much of its length.
- Mile 16.3
 BE-137. Lewis C. Stevens. Vermont

 VI
 The two old slides on this property remain active with the upstream slide 200' long by 30' high containing two leaning trees and the downstream slide 250' long by 30' high raw at the top with weed growth at the toe. There is a birch tree sliding and leaning on the slope with cow paths leading to edge of water.
- Mile 16.1 to 15.8
 BF-260, E. J. Farwell, Est., New Hampshire

 NN
 The 10' high silt bank is active with trees down and ice scars on the slope,
- Mile 16.05
 BF-136. Floyd C. Eastman. Vermont

 VT
 This 45' high bank is active again with trees

 leaning and sliding down in the water. The 1962

 break is active again. [See Picture B-20]

Wile 15.75 to 15.55 VT VT VT BF-132 and EF-131. Margaret C. Haskett and Arthur F. Putnam. Vermont This section remains stable. [See Picture B-22] A braced ferce post at the top of the slope in 1984 is now gone.

ID 6259

-6-

M11e 15.65 to 15.2	BF-238. J. H. Farwell. New Hampshire The 20' high slide is stabilizing. There is a house approximately 15 feet from the top of slope. [See Picture B-21] There is an old slide at Mile 15.5 with large trees down on the slope and in the water. [See Picture B-23] The remaining 700' long by 30' high bank is active with dead trees on the slope and in the water. [See Picture B-24]
Mile 15.3 to 14.9 NH	<u>BF-237. Roxle K. Dunmore, New Hampshire</u> This 30' high by 2,000' long bank is now very active with many trees undercut, leaning, sliding, and down in the water. ESee Picture C-11
<u>Mile 14.3 to 14.1</u> NH	BF-235, Mattle J. Loveland. New Hampshire This 1,000' long low wooded bank is slightly active. As noted in 1974, the island opposite this property is gone.
Mile 14.15 VT	BF-127, Paul Gilloll, Vermont This 500' long by 10' high bank is now inactive.
Mile 13.95 VT	<u>BF-126. Arthur Putnam. Vermont</u> The raw area, about 300' long by 15' high with sliding trees on the slope, is still healing. A 30" maple tree is sliding and leaning halfway on the slope.
<u>Mile 13.8</u> NH	<u>BF-225. Harry N. Whitmore. New Hampshire</u> The 40' long by 30' high break, first noted in 1962. Is now 300' long and very active with trees Teaning and down in the water.
Mile 13.8 to 13.55 VT	BF-125. Adim T. Putnam. Vermont This steep silty bank 20' high remains slightly active with sods on the slope. Beaver slides were noted in the riverbank silt from the cornfield to the river. [See Picture C-2]
Mile 13.6 NH	<u>BF-226, Alex Raymo, New Hampshire</u> A new 40'long by 40' high slide is still active.
Mile 13.4 NH	BF-227, George L. Farron, New Hampshire A 5' high undercut bank with growth overhanging the top of slope is slightly active. ESee Picture C-33
Mile 13.2 to 13.0 NH	BF-228, Wellington Curtis, New Hampshire This 10' high silt bank is active again. [See Picture C-4]

ID 6269

-7-

Mile 12,9 to 12.7 NH	<u>BF-228 and BF-229. Mellington Curtis</u> and Ulvsses S. Taliman. New Hampshire The upstream end is stable and healing due to new rip-rap on bank. [See Picture C-5] This low bank remains slightly active with sods on the slope and a cluster of maple trees at top of slope. [See Picture C-6]
<u>Mile 12.6 to 12.2</u> NH	BF-229. Ulysses 5. Tallman. New Hampshire This long silty 10' high bank continues to be active, raw, and undercut with numerous sods at the river's edge. The fence posts remain at the top of the bank with 3 posts over the bank. [See Picture C-8]
Hile 12.5 to 12.1 VT	New England Power Company, Vermont This area is intermittently active with 10' high banks and sod on river edge. [See Picture C-7]
Mile 12.4 to 12.3 VT	BE-BE, Frank W. Corliss, Vermont This 300' long by 5' high stit bank remains active.
Mile 12.2 to 12.0 NH	BF-217. Boston and Maine Railroad. New Hampshire This 1.000' long section is still active with numerous poplar trees down and leaning on bank.
<u>Mile 11.5 to 11.0</u> VT	BF-86. Vital Blais, Vermont A rip-rapped section on the upstream end remains stable. A 400' long by 15' high bank with many bank swallow holes is very active and raw with sods at the edge of the river. The road is approximately 20' from riverbank edge. [See Pictures C-10 thru C-18]
Mile 11.5 to 11.2 NH	BF-217. Boston and Maine Railroad. New Hampshire This 50' high bank continues to be raw at the downstream end for 150 feet. There are trees sliding and down with undercut sods on the slope. [See Picture C-9]
M1Te 11.1 to 10.5 NH	BF-218. G. D. Austin. New Hamoshire This bank is now inactive. Some poplars at the top of slope are undercut. Offset measurements show a 28-year erosion of 17.5 feet through 1982. Refer to the 1982 report for the erosion tabulation.
Mile 10.6 to 10.2 VT	BF-840, Ellen M. Butterfield, Vermont This area is now inactive. Both rip-rap and ledge have kept bank stable.

ID 6269

-8-

<u>Mile 10.5 to 9</u> NH	<u>.8 BBM Railroad, New Hamps</u> This 30' high slide rem sliding and down in wat high slide remains acti water, [See Picture C-	<u>hirg</u> ains active with trees er. A 200' long by 40' ve with trees down in 1 9]
<u>Mile 9.2 to 9.</u> MH	<u>BF-213, J. C. Fairbroth</u> This 100' long area is moorings and recreation [See Picture C-20] Dow by 10' high active sect with sods on slope and leaning. Precast concr used for stairway to ri	er. New Hampshire now cleared out for boat along shore. Instream is a 1,000' long fon along the Town Park trees undercut and ete bulkhead on bank is ver. [See Picture C-21]
Mile 9.2 to 9. NH	 BF-212, W. E. Corliss. The upstream area 200' and now connected to th feet long in 1977. The now 1,000' ong with so undercut and Teaming. 	New Hampshire long by 10' high is active e downstream area, 30D total area affected is ds on the slope and trees
Mile B.7 VT	BF-76, R. N. Dent, Verm This 40' high bank, wit and dead trees in the w [See Picture C-22] An inactive bank, [See Pi	ion <u>t</u> h an old slide 75' long ater, is healing. n existing dock remains on cture C-23]
<u>Mile 8.15 to 7</u> VF	.7 BF-76, R, W. Dent, Verm The upstream end of thi to be raw at the top wi indicating moderate act of this 10' to 15' high to be undercut with sod water. Banks are very vertical. [See Picture	ont s 30' high bank continues th brush at the bottom, ivity. The downstream end steep raw bank continues s and some brush in the active and nearly C-241
<u>Mile 7.5 to 7.</u> NH	5 BF-200, S. A, Richardso This high bank shows mo leaning pine sliding on ISee Picture D-11 The with a 40" pine at the	n, New Hampshire derate activity with a 30" the slope downstream end is active bottom of the slope.
<u>Milu 7,2 to 6.</u> NH	2 New England Power Compa About 2,000' of this ba the Army Corps of Engin erosion and protect the sewage treatment plant' [See Picture D-2] The treatment plant has rip area downstream along b	ny. New Hampshire nk has been rip-rapped by eers to arrest the bank Town of Charlestown s lagoon. riverbank upstream of the -rap placed at an outwash anking. [See Picture D-3]
<u>Mile 6.6</u> VT	BF-75, L. R. Bigelow an This slide is healed an [See Picture D-4]	d BF-74, NEP, Vermont d is inactive.
ID 6269	-9-	AJM/CGK: May 1991

9

Mile 3.5 to 3.3 VT	BF-61. New England Power The 300' long area down landing is now inactive upstream end and raw do are approximately 15 fer at the picnic grounds.	r Company, Vermont stream of the old boat with weed cover on the wistream. Utility poles et from the top of slope
Mile 3.3 to 2.4 NH	BF-176, BF-175a, New End New Hampshire This 1500' low silty bas undercut sods. [See Pictures D-12, D-13]	aland Power Company. nk remains active with 3. and D-141
<u>Mile 2.2 to 1.9</u> VT	BF-57a. Rutland Railroad This 10' high sandy grau sustained some loss sind Railroad" hid a spur tra top about 15 feet back, susceptible to wind and See Picture D-151 At M' and rocks have been dum guily. This area is sta 12' high area just down	d Company. Vermont vel bank is active and has ce 1977. The "Steamtown ack parallel to the bank This bank is very wave action. ile 1.95, concrete slabs ped over the slope at a able, but a 200' long by stream is active.
Mile 1.75 to 1.2 VT	OF-53a, OF-52, New Engli This low active bank has still in good condition remains undercut and lea	and Power Company, Vermont s some rock protection . A 24" beech tree aning since 1977.
Mile 1.45 to 1.2 NH	BF-173b, Nev England Pow The rip-rap placed in 19 condition. [See Picture a slide 50' long by 12' trees sliding and in the	wer Company, New Hampshire 964 remains in good a D-161 However, there is high just downstream with e water.
Mile 1.2 NH	BF-172b. Crav Oil Compar This 35' high silt bank active with the top of I trees and brush sliding water. ESee Picture D-	ny. New Hampshire continues to be very bank being undercut and down the face to the 17]
Mile 1.1 to 1.0 NH	BF-172b, Cray Oil Compar A 50' long by 20' high I raw areas. Some boulder placed on the slope to I House is now approximate top of the slope. [See long by 20' high raw see at top of slope remains [See Picture D-19]	ny. New Hampshire bank is active with many rs and trees have been help control slides. ely 50 feet away from the Picture D-18] A 200' ction with leaning trees active.
<u>Mile 0.6</u> VT	BF-50, Rutland Railroad, The large rock slabs dur erosion protection are s condition. [See Picture	<u>Vermont</u> mped over the bank for stable and in excellent es D-20 & D-21/Crew]
ID 6269	-11-	AJM/CGK: May 1991

Mile 0.5 NH	New Hampshire Bank The intermittent activity between the log yard boat landing and the steel arch bridge is slight. Concrete slabs have been placed on the slope just downstream of the boat landing. [See Pictures D-22 & D-23]
Mile 0.2	Connecticut River Downstream picture of the new highway bridge, which replaced the steel arch bridge in 1983. [See Picture D-24]

Attachments

Attached herewith is a complete set of double letter size FERC Project Boundary Maps (24 sheets) with the bank slides and photograph locations shown thereon.



-12-

AJM/CGK: May 1991

11




























































































Appendix D – Bellows Falls Impoundment Erosion Site Comparison: 1997-2008 Bellows Falls Impoundment Location 1



1997











Bellows Falls Pool – Location 4
























Bellows Falls Pool – Location 10





Appendix E – Vernon Impoundment Erosion Site Comparison: 1997-2008 Vernon Pool – Location I



1997



Vernon Pool – Location J





Vernon Pool – Location K



1997

No photo in 2008

Vernon Pool – Location L





Vernon Pool – Location M







Appendix F – Examples of Vernon Impoundment Erosion in 1954

VERNON FOND BANKS INSPECTION SEPTEMBER 2 AND 3, 1954

Ceneral

The inspection of the erosion of the banks between Bellows Falls and Vermon Dam was made on September 2 and 3, 195h. Members of the party included H. E. Stockwell from the Shelburne Falls office, F. D. Meader from the Littleton office, and R. F. Cascadden from the Boston office.

The discharge from Bellows Falls was about 15,000 c.f.s. at 5:00 a.m. September 2nd due to heavy rains during "Hurricane Carol," At this flow observation of banks below water line was impossible.

In most all cases the banks had not changed a great deal since the observations made in 1953. Krosion occurred at the same places and new breaks were only confined to small local bank slides.

Due to the abundance of rain this summer, woods and brush covered many slopes that show raw faces in the late spring.

Since the eroding banks occur at the same mileages as last year no attempt to give descriptive details of the banks composition etc. is made in this report. It is suggested that the 1953 report be kept at hand in order to get these descriptions and for comparison of photographs which in a great many cases speak for themselves.

The best was transferred from the Bellows Falls Log yard to a point below the tailrace on the Walpole side of the river the first thing Thursday merning, September 2, 1954.

Redacolor photos were also taken of the banks in Vermon Fond for experimental purposes as in Bellows Falls Fond and are contained in a separate folder for comparison with black and white prints made from the same negatives. This will be circulated for observation and comments by interested parties.

The following notes, pictures etc. were made traveling downstream and are so recorded to facilitate future observations made by boat.

Inspection Notes

Thursday, September 2, 195h

Mile 30.7 to 30.35 Vt. bank. W. S. Powers property. V-409

This bank has not changed in appearance and still presents a raw, silty face with some weeds. The large elms at upstream portion of bank still stand though badly buffeted by "Hurricane Carol."

See picture No. 13952, page 2-A, looking upstream along this bank. Mile 29.0 N. H. bank. C. Emery. V-139 (Opposite Cobb Brook).

No change has occurred in this 100 foot silt bank.

Mile 28.95 to 28.65 N. H. bank. C. Reery V-439 and C. Angier V-438.

This 25 foot high bank has become well weed covered this season, although it is composed mostly of silt. Very little eroding has been noted along this bank in recent years.

Mile 28.5 Vt. bank. Abeneque Machine Co. V-395.

This 400 foot section of wooded bank shows little change. Some trees as shown in picture No. 13953 are undercut and leaning over water, page 2-A, looking upstream.

Mile 28.0 Vt. bank. Anders Melson. V-394 (Below Walpole Bridge).

This 400 foot section of bank remains about the same with more weeds in evidence this year than last. The top of the bank has not cut back a great deal as noted in relation to the fence which parallels the top of this bank.

Picture Nos. 43954 and 43955 are views looking directly at this bank, pages 2-A and 2-B.

Mile 25.55 Vt. bank. W. H. Bent. V-383 (Nouth of Mill Brook).

These banks are pretty well brush and tree covered with no change in the raw banks at the mouth of Will Brook.

Mile 25.4 H. H. bank. Fanny Mason property. V-431.

No change has occurred along this wood covered 400 foot silt bank.

Mile 25.15 to 2h.5 Vt. bank. John Trybulski property. V-381.

This bank along its entire length continues to be active. The slopes are steep, raw and undercut.

The large trees shown in picture No. 13956 are also leaning over the water this year due to further undercutting. No. 13957 shows the bank, looking upstream. Page 2-B. Picture Nos. 14151 and 14152 also show these banks above and below Fullas Brook on page 2-C.

Mile 24.55 to 24.4 M. H. B. bank. Fanny Mason. V-431 and B. B. Knapp. V-430.

The upper section remains steep and practically devoid of vegetation while the lower has a good growth of weeds.

See picture No. 13958, looking directly at this bank, and No. 13959 looking upstream from vicinity of the mouth of Great Brook. Fage 2-D. Nile 21.3 to 21.0 Vt. bank. E. E. Putnam. V-379.

No change was noted in this section of 20 foot high silt bank. The old slides are only slightly active at lower part of banks. Nile 24.2 to 24.0 N. H. bank. E. B. Knapp. V-429.

This bank is moderately active and good cover of weeds blankets most of the raw silt face. The large elm shown in last years photo #h2012

-2-



Picture No. 13952

2-1

Vt. bank Mile 30.5 W. S. Powers V-409

Looking upstream



Picture No. 13953

Vt. bank Mile 28.35 Abenaque Machine Co. V-395

Looking upstream



Ficture No. 43954

Vt. bank Mile 28.0 Anders Nelson V-394

1

(Just below Walpole Bridge)







Mile 24.2 to 24.0 (Cont'd.)

still stands though undercut. See picture No. 13960, page 2-D, looking upstream.

Mile 23.3 N. H. bank. S. J. Chickering V-h25.

This h00 foot section of bank shows some activity since last season. There has been some cutting back of the bank and a few small trees are undermined, but the top of bank has not receded noticeably.

See picture No. 13961 page 3-4, looking at a section of this bank.

Mile 23.1 to 22.9 Same property (Mouth of Houghton Brook)

The willow sprouts that were set on bank above Houghton Brook seem to be growing very well and the bank has not changed in appearance above these sprouts. See picture No. h3962.

The bank below the brook also locks about the same. More weeds cover the slopes this season. See picture No. 53963 page 3-A, looking upstream along this bank.

The B. & M. R.R. were digging a trench with a shovel west of the tracks from a point in the vicinity of the town line, northerly to the vicinity of a gully 500 feet upstream. Sheet piling had been stacked along the bank and it looked like they were improving drainage along the slope which apparently contained blue clay.

Mile 22.45 to 21.6 Vt. bank. E. T. Hubbard V-338 ("Putney Meadows").

The banks below the mouth of Chase Brook had not changed and at this flow the large gully at the head of "The Meadows" contained water. This is the gully caused by the swirl pool in the 1936 flood.

See picture No. hh153 page 3-B, looking upstream along this bank.

The bank below the gully mouth shows some scouring. See picture No. hbl5h page 3-8.

From this point downstream 1500+ feet the banks are made up of old silt slides, in some cases slightly active, and in others brush and small trees have taken hold.

See picture No. 14155 page 3-B looking upstream.

At the downstream end of this bank near bend, the wooded bank is steep and raw and the remains of some large trees can be seen at the river edge.

See picture No. 44156 page 3-8 looking upstream.

Mile 21.35 to 21.0 N. H. bank. S. J. Chickering V-242-243.

The banks along upper section of property remain unchanged and inactive with a good covering of weeds and grass.





At mile 20.9, the 300+ foot meadow bank remains steep and undercut at the upper section while the lower section is covered with grass and weeds. See picture No. h396h page h-A, looking downstream at this bank.

Mile 20.6 N. H. bank. P. P. Action V-240 (Mouth Mill Brook).

The banks along this section show some undercutting and a few trees are leaning and falling into river. The bank below the brook shows greatest activity with one dead tree in river and its face is steep and raw.

The two large elms with roots exposed still stand in vicinity of the top of the bank.

See picture No. 13965 page h-A. looking downstream along this bank.

No change has occurred to banks at downstream end of property. See picture No. h3966 page h-B, looking upstream.

Mile 20.7 to 20.4 Vt. bank. E. T. Hubbard. V-337 (D.S. end of "Putney Meadows").

This 15 foot high silt bank has not changed and is kept raw by cattle pastured on meadow above.

See picture No. 14157 page 1-A, looking downstream at this bank.

Noon: September 2, 195h.

Mile 19.7 to 19.15 Vt. bank. H. W. Frost. V-335.

This bank remains moderately active with some undercutting and sliding of small trees. See picture No. 13967 page h-B, looking upstream at upper section and No. 14158 showing faulting meadow bank above East Putney Brook, page h-B.

The meadow bank below the brook mouth is quite active with large sods having broken off recently. See picture No. 13968 page h-D, looking upstream.

Mile 17.9 to 17.h N. H. bank. Chesire County Farm. V-236 (Formerly R. L. Blood).

The two small slides at upper end of faulting bank have not changed a great deal. Some dead trees lie on the face of the d.s. slide.

The banks to Mile 17.7 have become brushed over somewhat this season. See picture No. 13969 page h-D, looking downstream.

The bank from Mile 17.7 to 17.6 is moderately active with undercutting and sods breaking off. This raw silt bank seems to be more active than last year. See picture No. h3970 page h-D, looking upstreamalong this bank.

Mile 17.h N. H. bank. C. M. Moore. V-235.

The high slide reported at lower end of V-236, upon further inspection was found to be about on the property line and mostly below it.

Link VERNON FOND Picture No. 43964 N. H. bank Mile 20.9 S. J. Chickering V-243 Vernon Pond #439 9-2-54 Picture No. 43965 N. H. bank Nile 20.7 Peter P. Action V-241 (Formerly C. M. Moore) Vernon Picture No. 44157 Vt. bank Mile 20.6 E. T. Hubbard V-337 Looking downstream at bank above brock at d.s. end of "Putney Meadows"





Mile 17.h (Cont'd.)

Very little change has occurred in the appearance of the slide although its face remains perpendicular at top and devoid of vegetation, while the section that slipped down the bank still has fairly large trees still standing. Quite a few trees are still in the river as shown in picture No. 14159, page 5-A, looking directly at this high bank.

Mile 17.45 Vt. bank. R. W. Hallock. V-331.

This 200' long and 10' high bank remains slightly active. A 35-foot elm has fallen at upstream end of slide, and a wash hole appears in silt bank below.

Mile 17.0 N. H. bank. C. M. Moore. V-235.

The-100-foot slide at this location shows some action. Small pine that was undercut last season is now falling. Other small trees to follow. This bank is heavily wooded.

Mile 15.2 N. H. bank. S. B. Lund. V-232.

This h00-foot section of silt slides, 10 to 15 feet high remains about the same in appearance. Its face has a fair cover of low growing weeds. See picture No. hhl60, page 5-4, looking upstream.

Mile 15.7 to 15.4 N. H. bank. L. W. Churchill. V-231 (Opposite Futney Station).

This bank remains active, but no large amount of bank has broken off since last year. The face of the bank, being devoid of vegetation, shows washlines of various flow elevations this year.

The top remains undercut and steep. See picture Nos. hhl61, bul62, and bul63, pages 5-A and 5-B.

Mile 14.8 Same property. V-230.

The high 40' slide at this location has not changed much since 1953. The 25' pines that were mentioned as being undercut last year are now leaning over bank.

Mile 14.6 to 14.4 Vt. bank. Vt. Valley R. R. V-204 (Mile 68)

This section of track and the banks above appear to be unchanged since observations made in the spring.

Picture No. 44164 shows the cinder remedial work done on the 1952 slide.

Mile 14.2 to 14.0 N. H. bank. L. W. Churchill. V-226 (Opposite Canoe Brook).

This low silt bank has not changed, but does have more weeds on its surface this season. See picture No. h3971, page 5-H, looking upstream.





Wile 13.75 Vt. bank. Vt. Valley H. R. V-284.

The small slide noted at this point in 1953 was completely vine andweed covered.

No change was observed in the small slides on the N. H. bank on the F. L. Carey property. V-227.

Mile 13.15 Vt. bank. A. H. Bennett. V-262 (U.S. of mouth of Salmon Brook).

The breaks along this bank have increased to about 200 feet in length and vary from 6 to 15 feet in height.

One leafed out elm lies in the river, while a sycamore is undercut, and three h0-foot pines are still only a few feet back from the top of the slope. See picture No. 13972, page 5-8, looking upstream. This land is between the railroad and the river and is unused.

Mile 12.95 to 12.9 N. H. bank. H. J. Willette. W-197.

This 300' section of 15-foot bank has not changed.

See picture No. 13973, page 6-A, looking downstream.

Mile 12.55 N. H. bank. C. E. Chickering. V-195.

The old slides remain inactive along this bank and are mostly wood covered, except for a short section behind a new house being constructed.

Hile 12.4 N. H. bank. Town Road.

The road has been straightened and raised across this low section making it now passable at higher flows. In the past this location was one of the first to become inundated.

Mile 11.9 to 11.7 M. H. bank. West Chesterfield River Road (Improved Section).

The rip-rapped section of bank appears in good condition. There has been some surface washing along the slope and the guide fence cable is still broken opposite turn to "Hill Road," but no damage of a serious nature was observed. Picture No. 44165, page 6-4.

Mile 11.7 Vt. bank. E. H. Simoon and Son. V-279.

The 200' slide at this location has not changed.

Hile 11.6 to 11.5 H. H. bank. C. T. Chase. V-191.

This bank continues to be moderately active with the banks remaining steep, raw and undercut. See picture No. bhild showing the upper section. Page 6-4.

The river bank just upstream from mouth of Cats Hane Brook is also active. Picture No. 1397h, page 6-R, shows a typical section of this bank. The land is unused.





Mile 11.0 to 10.3 Vt. bank. R. M. Peltier. V-275.

This long, active section of meadow bank continues to recede, but action is very slow. The surface remains raw, steep, and devoid of vegetation.

See picture No. 44167, page 6-B, looking downstream along the bank.

The banks below the Chatterton lot remain moderately active.

Mile 10.45 Vt. bank. H. M. Chatterton, Jr. V-275.

The banks along this property have now receded back to the small willow trees. Picture No. hhl68 shows these trees. Page 6-B.

Mile 10.2 N. H. bank, H. L. Williams. V-184.

This 300 foot section of bank has not changed, except that three trees are now beginning to lean out over river.

Mile 9.3 Vt. bank. R. M. Peltier. V-87.

The 200' long and 10 to 25 foot high slide at this location remains inactive.

Mile 9.0 Vt. bank. American Optical Co. V-86 (Above "Gulf Bridge").

The upper portion of this high slide remains raw and steep with the same 3 small oak trees undercut at the top of the bank, as shown in picture No. 13975, page 7-4, looking directly at this bank.

Wile 8.55 Vt. bank. H. G. Thomas. V-83.

This 200' section of 10-foot silt bank remains moderately active. Small trees are leaning over the river and a few have fallen since 1953. A camp with a boat landing for speed boat is just downstream from this break.

Mile 8.45 N. H. bank. Chesterfield Town Road, Vicinity of V. P. Schmitt.

The gravel and stone rip-rap repairs made to this section in 1952 remain in good condition.

Mile 8.3 Vt. bank. L. H. Moyes. V-81.

This low 100-foot bank is active, and the silt face remains steep and rew.

Three small trees were in river, but apparently went in due to "Hurricane Carol."

Friday, September 3, 195%.

Mile 5.55 Vt. bank. Energine Co.

One willow tree is down in setback between R.R. fill and Energine plant. Probably due to hurricane, although roots were noted as being exposed in 1953.



Mile 5.55 (Cont'd.)

This 100-foot long bank is about 10 feet high and has a steep, raw silt face.

Mile h.h Wt. bank. Woodward Lumber Co., Inc. V-23.

The 200' section of bank remains moderately active with sode having broken off this year. The face of slide remains steep and raw.

See picture No. 13976, page 7-A, looking upstream at this bank.

Mile h.2 Vt. shore. Central Vt. R.R.

The G.V.R.R. was again improving the ballast of their track through this section between Vernon and Brattleboro. Tamping machines were working the gravel ballast.

Mile h.O Vt. bank. Harris-Dunham Fitts Estate. V-22.

This 300'+ bank remains active with some cutting of bank since 1953. Some small trees are lying in river and more are to follow due to undercutting.

See picture No. 13977, page 7-4, looking downstream.

Mile 3.97 to 3.8 N. H. bank. Conn. River Railroad. V-115.

This bank remains very active along its entire length. The 15 to 20 foot slope is raw, steep, and continuously undercutting due to sand and silt composition.

At downstream section of bank many small trees have fallen over bank and one 8-inch pine lies in the river.

A double 50-foot maple is undercut at downstream end of these breaks.

See picture No. 46169 and 46170, page 8-A, looking upstream.

Mile 3.35 Vt. bank. Central Vt. R.R. V-20.

This bank remains unchanged as evidenced by comparing 1953 photo No. h20h9 in 1953 report with 1954 picture No. 44171, page 8-A.

Mile 3.15 Same.

This high bank is non-active and no change was observed from last year's observations.

See picture No. 14172, page 8-4, looking directly at this slide.

Mile 2.6 and 2.35 N. H. bank. Conn. River R.R. V-110 and 109.

The slides at these points are now well brushed over and are inactive. They are on unused land well away from the railroad itself.



Mile 1.1 N. H. bank. Conn. River R.R. Culvert. V-104.

The culvert repairs made in 1952 by the railroad are in good condition.

See picture No. h4173 looking through the culvert, page 9-A.

Mile 0.75 N. H. bank (Same) V-101.

This high sand & silt slide shows some activity along the toe of slope which has washed back, thus making it more precipitous and vulnerable from slides up above.

See picture No. 13978, page 9-4, looking at this bank.

Mile 0.65 N. H. bank. C.R.F. Co. V-100.

Picture No. LA174 shows high sand and silt slide at this location. The beach is composed of silt and gravel and slopes off gradually from toe of slide.

Mile 0.35 "Vernon Neck"

Picture No. hhl75 is a general view looking downstream at upstream side of "The Neck."

Trees and brush were cut to protect banks from erosion.

Mile 2.2 to Dam Vt. bank. C.R.P. Co.

The banks along this section are in good condition, and no changes were noted.

Conclusions

As noted herein, there have been no radical changes in the slides noted in 1953 as to location, enlargement, etc. Where the banks are steep, devoid of vegetation, and exposed to winds, a gradual recession continues and although this receding was difficult to observe in just one year's lapse of time, it is believed that photographs in time, when compared with those originally taken in 1953, will show this progressive action.

The banks have not undergone any heavy ice action, with abnormally high flows in the past few years so many banks that are vulnerable to this now appear to be non-active or healed over by brush grass and weed cover.

The next time the inspection is made it would be well to do it sometime in late May before foliage and weeds get started and when the silt from the spring'e high water still shows on the banks. Photographs taken during previous inspections of interested properties at this time of year gave very good detail.





From a comparison of photos, on properties involved in the "Bellows Falls Flowage" cases, taken in 1945 through 1948 by H. M. Nelson, it appears that some of the banks involved have improved in appearance due to slope stabilization, and in some cases weeds and grass have covered the silted banks.

Other banks such as those on the Trybulski, L. W. Churchill, and R. M. Peltier properties remain active and are progressively receding at a rate that varies with the spring flows, ice conditions, etc.

Attachments:

Ons sot of double lettersize F.P.C. Project Boundary Maps, Exhibit K-2 (14 sheets) with eroding bank and picture locations colored thereon.



Appendix G – Turners Falls Impoundment FRR Summary Maps, 2008

Riverbank Score - Section 2


Riverbank Score - Section 3





Appendix H – Turners Falls Impoundment, Photos of Repaired Erosion Sites



Site 7 – Flagg, 1998



Site 7, Flagg (South), 2008 (from Maintenance Inspection Report)



Site 4 – Urgiel (upstream), before 2001



Site 4 – Urgiel (upstream), 2008 (from Maintenance Inspection Report)



Site 6 – Skalski, prior to 2004



Site 6 – Skalski, 2008 (from Maintenance Inspection Report)

Appendix I – Turners Falls Pool, Natural Stabilization Processes



1996 - Eddy-induced erosion downstream of Vernon Dam



2008 – Eddy-induced erosion downstream of Vernon Dam

Natural stabilization processes 1996-2008 downstream of Vernon Dam



Right Bank near downstream end of Stebbin's Island - 1998



Right Bank near downstream end of Stebbin's Island - 2008



Riverbank Segment with some low bank vegetation - 1998



Riverbank Segment with dense low bank vegetation - 2008



Close-up of low bank aquatic vegetation - 2008

Appendix J – Holyoke Impoundment Erosion Site Comparison: 1997-2008 Holyoke Pool - Location A



1997



Holyoke Pool – Location B





Holyoke Pool – Location C





Holyoke Pool – Location D





Holyoke Pool – Location E





Holyoke Pool – Location F





Holyoke Pool – Location G





Holyoke Pool – Location H





Appendix K. Riverbank Erosion on other Rivers



Yellowstone River - Yellowstone National Park



Yellowstone River – Yellowstone National Park



Yellowstone River - Yellowstone National Park



Yellowstone River – Yellowstone National Park



Yellowstone River – Yellowstone National Park



Yellowstone River – Yellowstone National Park



Yellowstone River – Downstream of Yellowstone National Park



Yellowstone River - Downstream of Yellowstone National Park



Middle Fork Flathead River – Glacier National Park



Middle Fork Flathead River – Glacier National Park



Avalanche Creek – Glacier National Park



Avalanche Creek – Glacier National Park



Avalanche Creek – Glacier National Park



Avalanche Creek – Glacier National Park



Middle Fork Flathead River – Glacier National Park



Middle Fork Flathead River – Glacier National Park



Middle Fork Flathead River – Glacier National Park



Middle Fork Flathead River – Glacier National Park



Middle Fork Flathead River – Glacier National Park



Flathead River - Montana



Bow River - Banff National Park, Canada



River in British Columbia



National Creek - Wrangell-St. Elias National Park, Alaska*



National Creek - Wrangell-St. Elias National Park, Alaska*

*After Hart-Crowser, 2005, "Geomorphic Assessment National Creek Kennecott, Alaska"



National Creek – Wrangell-St. Elias National Park, Alaska



National Creek – Wrangell-St. Elias National Park, Alaska



South Fork Skokomish River, Washington



South Fork Skokomish River, Washington



Lower Osage River, Missouri



Lower Osage River, Missouri



Rio Sao Francisco, Brazil



Rio Taquari, Brazil