

FERC Scoping Meeting
January 30, 2013
Relicensing of Northfield Mountain Pumped Storage Project


Michael Bathory, presenting landowner representing Maryanne Gallagher, Alan Wallace, and Barbara Watson River Road conservation land owners. Conservation Restrictions held by the Massachusetts Department of Conservation and Recreation in Gill, Massachusetts. Flowage rights held by the landowners.

These landowners are members of Landowners and Concerned Citizens for License Compliance (LCCLC) and the Connecticut River Streambank Erosion Committee. They are assisted by the Connecticut River Watershed Council which serves as a nonprofit umbrella organization for LCCLC.

Michael Bathory and Maryanne Gallagher
144 River Road
Gill, Massachusetts 01354

Alan Wallace, and Barbara Watson
143 River Road
Gill, Massachusetts 01354

Arrows indicate the Wallace/Watson and Bathory/Gallagher sections of riverbank upstream from Northfield Mountain picnic area and tailrace.





Phase III Bank Restoration for the Connecticut River
in the Town of Gill, Massachusetts
Bathory/Gallagher & Wallace/Watson
Conservation Land



Construction access road
as seen during October 5, 2012 Relicensing Site Tour.

Year 1 construction on Bathory/Gallagher and Wallace/Watson riverbanks December 2012. Year 2 to be completed in Fall 2013.



Attempts to buttress eroding Bathory/Gallagher banks, December 2012. ⁵



Examples of erosion on Bathory/Gallagher riverbank as seen from construction road, December 2012.



More examples of erosion on Bathory/Gallagher riverbank
as seen from construction road, December 2012.



Examples of erosion on Wallace/Watson riverbank
as seen from construction road, December 2012.
Arrows indicate tree stump seen in next set of photos.



Photos of tree at toe of bank in 1960 and the stump of the same tree in 2012 demonstrating the erosion that has occurred over 52 years.

